

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D




FIG. 9




FIG. 10

No.	A1	A2	A3	CLK	M1 Q	M2 Q	M3 Q	M4 Q	M5 Q	M6 Q	M7 Q	CLR 1	CLR 2
1	—	0	0	0	—	—	—	—	—	—	1	1	0
2	1	1	0	0	1	—	—	—	—	—	1	0	1
3	1	0	1	0	0	1	—	—	—	—	1	0	1
4	1	1	1	0	1	1	—	—	—	—	1	0	1
5	0	1	0	0	1	1	1	1	1	1	0	0	1
6	0	0	1	0	0	1	1	1	1	1	0	0	1
7	0	1	1	0	1	0	1	1	1	1	0	0	1

INPUT CLOCK

INPUT DATA \uparrow
12B INPUT START COMMAND OV UV 50% OR

OUTPUT CLOCK 

D OUTPUT START ↑ COMMAND

OUTPUT DATA

OV UV 50% OR